



102220

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION III  
841 Chestnut Building  
Philadelphia, Pennsylvania 19107-4431

November 17, 1994

Mrs. Jean Torgerson  
16 Allston Lane  
Hollywood, Maryland 20636

RE: Southern Maryland Wood Treating Site  
Hollywood, Maryland

Dear Mrs. Torgerson:

Enclosed are the analytical results from surface water samples that were collected in September 1994 at three locations in the west tributary at the Southern Maryland Wood Treating Site. Results show very low levels of volatile organic and base/neutral and acid extractable contaminants, the highest concentrations of which are found in the sample taken just outside the sheet pile wall. These results confirm that, under normal conditions, very little contamination is flowing offsite via surface water.

Also enclosed is the document Soil Cleanup Goals Modeling Using Multimedia Exposure Assessment (MULTIMED) Model, David M. Kargbo, Ph.D, U.S. EPA, October 1994, referenced in the Draft Focused Human Health Risk Assessment, Roy L. Smith, Ph.D., U.S. EPA, October 6, 1994, as we discussed during the conference call on November 2, 1994.

Please contact me with any questions at (215) 597-3167.

Sincerely,

Stephanie Dehnhard  
Remedial Project Manager  
DE/MD Section

cc: Joel Hirshhorn  
Judy Landau Pederson  
Raphael Guenther  
David Healy, MDE  
Site Repository

AR400195